

NO	PART DRAWING	AM./PCS.
1		2
2		2
3		2
4		4
5		4
6		2
7		2
8		2
9	4x16 C.SCREW	30
	4x12 C.SCREW	8

BC21-3DIA